

# Interim Reclamation and Stormwater Inspection

February 28, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504539

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 1.** Photo taken from the southern location, facing South. Photo illustrates that it appears trash blown off location has been picked up.



**Photo 2.** Photo taken from the western location, facing West. Photo illustrates previously identified unused equipment. Operator indicated a potential need; therefore, the Compliance Specialist is requiring a plug on the risers. Note- risers are disconnected from any potential gas source.



Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 3.** Photo taken from the wellheads, facing East. Photo illustrates unused has been removed.



**Photo 4.** Photo taken from the eastern location, facing Northeast. Photo illustrates the weedy vegetation within the BMP area and unused equipment remains.



Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 5.** Photo taken from the eastern location, facing North. Photo illustrates a spill of what appears to be non-E&P exempt waste from a Mobil Pegasus SAE 40 container. This will need to be reported to CDPHE and this appears to be a violation of Rule 906.  
Note- it does not appear any action has been taken since the previous inspection.



**Photo 6.** Photo taken from the eastern location, facing East. Photo illustrates stained soil/spill related to the compressor.  
Note- it does not appear any action has been taken since the previous inspection.

Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 7.** Photo taken from the eastern location on 2/10/2023. Photo illustrates poor housekeeping, as diesel fuel has spilled onto the ground. Note- Operator Operator has not installed secondary containment for materials handling and spill prevention practices for this piece of equipment.



**Photo 8.** Photo taken from the eastern location on 2/10/2023. Photo illustrates netting is in disrepair. Remove and properly dispose fluids from within the secondary containment. Note- Operator has not addressed this corrective action.