

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283092 Type: WELL API Number: 031-08835 Status: SI Insp. Status: SI

Workover

Comment: At time of inspection well was in process of P&A. At time of inspection company representative informed me they had set a plug at approx 3200' MD, and perfed above plug. At time of inspection rig crew was rigging down wireline equipment to TIH with work string to pump cement.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were cold, windy, cloudy, recent snow.	medinaj	02/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504439	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6041921