

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2023

Submitted Date:

02/27/2023

Document Number:

707800200**FIELD INSPECTION FORM**

Loc ID 334673	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	----------------------------------	---	-------------------	---

Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>1058 COUNTY ROAD 215</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>	ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
--	---

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284818	WELL	PR	08/20/2015	GW	045-12284	CIRCLE B LAND 34D-35-692	PR
285094	WELL	PR	10/29/2006	GW	045-12380	CIRCLE B LAND 44C-35-692	PR
285095	WELL	PR	11/02/2006	GW	045-12379	CIRCLE B LAND 44A-35-692	PR
285096	WELL	PR	10/30/2006	GW	045-12378	CIRCLE B LAND 34B-35-692	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 2/23/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP CB 6, at Location # 334673 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Inspection is conducted also for complaint on CB4 SWD. I witnessed in the time frame of inspections around CB4 SWD 3 bob tail trucks and 1 transport truck in the 4 hours of inspections at locations in close proximity to CB4 SWD.

C/A (stored/unused equipment, tank labels) from previous inspection document # 700703860 has not been completed.

During this inspection the following compliance issues were observed:

1. Stored/unused equipment (C/A date remains the same 5/11/2022)
2. Labeling on tanks missing info or not installed (C/A date remains the same 3/11/2022)
3. Random debris
4. Battery sign is illegible.
5. Plastic gas can in tank battery with heated tanks.
6. Access road and location not plowed only passable with 4 wheel drive

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is illegible.		
Corrective Action:	Provide proper and legible signage	Date:	03/27/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labeling on tanks missing info or not installed (C/A date remains the same 3/11/2022)		
Corrective Action:	Provide proper labeling	Date:	03/11/2022
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored/unused equipment (C/A date remains the same 5/11/2022)		
Corrective Action:	Remove unused/stored equipment	Date:	05/11/2022
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	03/10/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No <input type="text"/>			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	See stored/unused equipment for C/A		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	OTHER	HEATED STEEL AST		,	
Comment:	3 tanks are not heated					
Corrective Action:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	284818	Type:	WELL	API Number:	045-12284	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285094	Type:	WELL	API Number:	045-12380	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285095	Type:	WELL	API Number:	045-12379	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285096	Type:	WELL	API Number:	045-12378	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: [Access road and location not plowed only passible with 4 wheel drive. Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403333396	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6035994
707800204	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6035979