

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2023

Submitted Date:

03/08/2023

Document Number:

705000183

**FIELD INSPECTION FORM**Loc ID 437337 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251315	WELL	SI		OW	123-19118	HSR-ACORD 16-30	PA
443798	TANK BATTERY	AC	10/30/2015		-	ACORD STATE TANK BATTERY 34N-30HZ	EG

**General Comment:**COGCC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: <u>251315</u>	Type: <u>WELL</u>	API Number: <u>123-19118</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>443798</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

**Flowline**

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site      Size: 2"      Material: Carbon Steel  
Variance:      Age:      Contents:

Integrity Summary

Failures:      Spills:      Repairs Made:  
Coatings:      H2S:      Cathodic Protection:

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☒ 1103. Abandonment

Comment: Well (HSR-Acord 16-30) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403292682 received 01/17/2023. COGCC form 42 flowline pre-abandonment notice doc #403339450 received 03/07/2023. Flowline abandonment/ removal work is pending. Fenced excavations observed at the PA wellhead and facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are in process of removal. Oxy contract personnel were completing excavation and remediation work (historical) at time of inspection.

Corrective Action:      Date:

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403327649 received on 02/24/2023: During tank battery removal activities at the Acord 12 & 13-29A O SA Facility, historically impacted soil was discovered adjacent to the above ground storage tanks (ASTs) and produced water vessel (PWV). The tank battery is being permanently removed.	maclarej	03/08/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000193	Signage at PA well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044504</a>
705000194	View of location to west; flowlines removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044505</a>
705000195	Excavation and OOS GMR; view west	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044506</a>