

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2023

Submitted Date:

03/08/2023

Document Number:

696204752

FIELD INSPECTION FORM

 Loc ID 335780 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270319	WELL	PR	03/01/2019	GW	045-09528	CHEVRON 24D-17D	RI
270320	WELL	PR	03/01/2019	GW	045-09529	CHEVRON 24B-17D	RI
274732	WELL	PR	03/01/2019	GW	045-13380	CHEVRON 13D-17D	RI
274913	WELL	PR	03/01/2019	GW	045-13429	CHEVRON 14A-17D	RI
274915	WELL	PR	03/01/2019	GW	045-13430	CHEVRON 14D-17D	RI
335780	LOCATION	AC			-	CHEVRON-66S96W 17SESW	RI
427697	TANK BATTERY	AC	04/14/2009		-	CHEVRON-66S96W 17SESW	RI

General Comment:

On 3/06/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's CHEVRON-66S96W 17SESW Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Stormwater
- Secondary containment liner integrity.
- Signage

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at the 24B-17D well. Signs at remaining wells becoming illegible- maintenance advised.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/08/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire/panelling		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal pipe		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	<input type="text"/>				

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment is not sufficiently impervious to contain spilled or released materials; various holes/tears observed throughout liner.			
Corrective Action:	Maintain BMP to ensure containment is sufficiently impervious to contain spill or release			Date: 04/08/2023

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 270319 Type: WELL API Number: 045-09528 Status: PR Insp. Status: RI

Facility ID: 270320 Type: WELL API Number: 045-09529 Status: PR Insp. Status: RI

Facility ID: 274732 Type: WELL API Number: 045-13380 Status: PR Insp. Status: RI

Facility ID: 274913 Type: WELL API Number: 045-13429 Status: PR Insp. Status: RI

Facility ID: 274915 Type: WELL API Number: 045-13430 Status: PR Insp. Status: RI

Facility ID: 335780 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 427697 Type: TANK API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that BMPs to stabilize, as well as to tracking, degradation and sediment transport at the access road and Location entrance are missing or insufficient; tracking/degradation observed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 03/11/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204753	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044565