

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2023

Submitted Date:

03/09/2023

Document Number:

694100074

FIELD INSPECTION FORM

Loc ID 323639 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
,		cogccinspection@pdce.com	ALL INSPECTIONS
Hammond, Barney		Barney.Hammond@pdce.com	

General Comment:

This is an environmental inspection for Location ID 323639 Kielian 2-2 TB. Any corrective actions from previous inspections that have not been addressed are still applicable. PDC personnel (Jason Davidson) was on location at the time of this field inspection. Photos attached to document site conditions.

Location Construction

Location ID: 323639 CDP: _____

Comment: Field crews were on site undergoing excavation operations. A large open excavation approximately 50ft x 20ft x 10ft was underway with groundwater at about 8ft bgs.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: This is an historic spill location. Field crews were on site undergoing excavation operations. A large open excavation approximately 50ft x 20ft x 10ft was underway with groundwater at about 8ft bgs. Crews were removing impacted soil and groundwater.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: This is an historic spill location. Field crews were on site undergoing excavation operations. A large open excavation approximately 50ft x 20ft x 10ft was underway with groundwater at about 8ft bgs. Crews were removing impacted soil and groundwater. Work will be ongoing as excavation contiunes to expand both vertically and laterally.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100075	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6045872