

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2023

Submitted Date:

03/10/2023

Document Number:

708900094

**FIELD INSPECTION FORM**

Loc ID 335618 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Depaolo, Corey		corey.depaolo@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287572	WELL	PR	09/01/2020	GW	045-13001	UNOCAL-ENCANA 23D-4D	PR
288397	WELL	PR	09/01/2020	GW	045-13237	UNOCAL-ENCANA 24B-4D	PR
288398	WELL	PR	09/01/2020	GW	045-13236	UNOCAL-ENCANA 23B-4D	PR
288399	WELL	PR	09/01/2020	GW	045-13235	UNOCAL-ENCANA 24A-4D	PR
288400	WELL	SI	12/01/2022	GW	045-13234	UNOCAL-ENCANA 23A-4D	SI

**General Comment:**

COGCC Inspection Report Summary  
On 03/08/2023 at approximately 14:28 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC UNOCAL-ENCANA 23D-4D Pad. Location # 335618 in Garfield County Colorado. Location is located in a high priority habitat area. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Containment needs maintenance with a CA date of 03/30/2023
2. Flowline heating insulation open ended with a CA date of 03/17/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery signs weathered & starting to peel but still legible		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/1-866-580-9382		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire & Jersey barrier		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flowline heating insulation open ended		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.		Date: 03/17/2023
Type: Bradenhead	# 5		
Comment:	Unable to visually verify on 24A-4D & 23A-4D wells due to snow The 3 remaining wells have no form of pressure monitoring equipment located on bradenheads. All 3 bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Containment liner needs maintenance			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			Date: 03/30/2023

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>287572</u>	Type:	<u>WELL</u>	API Number:	<u>045-13001</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>288397</u>	Type:	<u>WELL</u>	API Number:	<u>045-13237</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>288398</u>	Type:	<u>WELL</u>	API Number:	<u>045-13236</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>288399</u>	Type:	<u>WELL</u>	API Number:	<u>045-13235</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>288400</u>	Type:	<u>WELL</u>	API Number:	<u>045-13234</u>	Status:	<u>SI</u>	Insp. Status:	<u>SI</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						
		Compaction				
Ditches						
Gravel						
		Gravel				
		Ditches				
Berms						

Comment:

Corrective Action:

Date:

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Equipment & Tanks & Berms for observed compliance issues.	smelserw	03/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900103	Inspection 708900094 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046563</a>