

Final Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 317498

Inspection Document #: 708200033

Weld County, CO

SWNW Section 14 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Facing northeast near pits. Photo illustrates rill and gully erosion occurring on location. No BMPs were observed on location to manage stormwater. Sediment laden stormwater was also observed to have migrated off location into adjacent lands (see Photos 5 & 6). Stormwater BMPs will need to be implemented immediately to prevent further off location degradation.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 2. Facing southeast, see comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 3. Facing northwest, see comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 4. Facing south from reclaimed area, see comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 5. Facing south, see comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 6. Facing north from adjacent land, off location. See comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 7. Facing north near separator and tank battery. See comments in Photo 1.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 8. Facing west near reclaimed well location. It appears the operator has performed final reclamation activities with evidence of contouring and grading, and removal of debris and equipment.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 9. Facing south, see comments in Photo 8.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 10. Facing southeast near pit; road drag observed on location. This is considered unused equipment and needs to be removed.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 11. Facing northwest near pit; pipe observed on location. This is considered unused equipment and needs to be removed.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 12. Facing northwest at pit. Sucker rod observed within pit is considered used equipment and needs to be removed.

Inspection Photos
Location Name: April 12-14
Location ID: 317498



Photo 13. Facing southeast; trash observed on the southern portion of the reclaimed well location.