

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2162 From entrance to location



Photo # 2163 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2164 Location



Photo # 2165 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2166 Location



Photo # 2167 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2170 Calibration info not conspicuously posted



Photo # 2172 Calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2180 Tank needs maintenance



Photo # 2181 Containment needs maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2182 Containment needs maintenance



Photo # 2183 Containment needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2169 Chemical BMP not maintained



Photo # 2184 Chemical BMP not maintained

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2187 Sediment transported into ditch, ditch needs maintenance



Photo # 2188 Sediment transported into vegetated area

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. Parachute MF10B E09 696 pad

Location # 335856



Photo # 2189 Sediment transported into vegetated area



Photo # 2192