

# Inspection Photos

3/13/2023

Operator: CHEVRON USA INC - 16700

Location #314696

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 1:** Photos 1- 8 taken from the Location and access road. Photos examples showing BMPs to stabilize the working pad and access road, as well as to minimize degradation, tracking and offsite sediment transport are missing or insufficient.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 3:** See comments under photo 1.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 5:** See comments under photo 1. Photo also shows tracking from access road onto Hwy 64.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 6:** See comments under photo 1. 6 foot measuring stock for reference.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



March 13, 2023

**Photo 7:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



March 13, 2023

**Photo 8:** See comments under photo 1.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 9:** See comments under photo 1. Photo also shows wellhead. Well repair appears to be “in process”.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



March 13, 2023

**Photo 10:** Photos 10-11 taken from the perimeter of the Location. Photos show Operator appears to have pushed soils beyond the perimeter of the working pad; soils observed covering vegetation; soils are unconsolidated and a pollutant source; BMPs to minimize off-site sediment transport from the soils missing or insufficient.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 11:** See comments under photo 10.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 12:** Photo taken from the east end of the Location. Photo shows disassembles well equipment improperly stored on the perimeter of the pad; equipment appears to be covered in production fluids; fluids evident within equipment and observed dripping onto the soil surface.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 13:** Continued from photo 12. Photo shows what appears to be produced fluids within the disassembled well equipment dripping onto the soil surface.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 14:** Photos 14-16 examples showing stained soils observed throughout the working pad area.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 15:** See comments under photo 14. 6 foot measuring stick for reference.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 16:** See comments under photo 14.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 17:** Photos 17-18 provide examples of trash/debris observed throughout the Location.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 18:** See comments under photo 16.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 19:** Photo shows tank on Location missing required labeling.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



March 13, 2023

**Photo 20:** Photo taken from the east end of the Location, facing east. Photo shows off-location areas previously undisturbed, that have been disturbed due to off-location travel by the Operator.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



**Photo 21:** See comments under photo 21. 6 foot measuring stick for reference.







**Photo 22:** Photo shows a Google Earth Aerial image of the Location. Areas outlined by the yellow polygon represents areas of new disturbance (see photos 20-21). Areas appear to be previously undisturbed, and outside of the designated working pad and access road.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314696



March 13, 2023

**Photo 23:** Cellar left uncovered.

