

Interim Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 455365

Inspection Document #: 708200026

Weld County, CO

NENW Section 29 T8N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 1. Facing north from the southeastern portion of the interim reclamation areas. Undesirable vegetation (e.g. kochia and russian thistle) and areas of bare soil were observed throughout the interim areas. It appears that the weeds have been managed previously with evidence of mowing.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 2. Facing southwest from the southeastern portion of the interim area. See comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 3. Facing west from the southeastern portion of the interim area. See comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 4. Facing northwest from the southern/central portion of the interim area. See comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 5. Facing northwest towards the western interim area. See comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 6 & 7. Close up photos illustrating bare soil and undesirable vegetation (e.g. russian thistle and kochia).

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365




Photo 8. Facing south from the topsoil stockpile. Photo illustrates debris and evidence of vehicle traffic on the stockpile.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 9. Facing east from the western edge of the pad. Photo illustrates rill erosion occurring within the interim areas that appears to have originated from a breached perimeter berm. (Hard hat for scale)

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 10 & 11. Close up photos; See comments in Photo 9.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 12. Facing northwest from the western portion of the pad; this portion of the interim area will need to be reclaimed once the pipeline work has been completed.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 13 & 14. Close up photos of open top tanks near the location's wells; the wildlife netting is inadequate and will need to be repaired or replaced to exclude wildlife entry.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 15 & 16. Close up photos of debris that needs to be removed.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 17 & 18. Facing southwest near production equipment. Photo illustrates tumbleweed accumulations within equipment; this is now considered debris and needs to be removed as it present a fire hazard.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 19 & 20. See comments in Photos 17 & 18.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photos 21 & 22. See comments in Photos 17 & 18.