

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2023

Submitted Date:

03/13/2023

Document Number:

708300180

FIELD INSPECTION FORMLoc ID 334269 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	
Byers, Jim		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210984	WELL	SI	05/01/1996	CBM	045-06742	SOUTH SHALE RIDGE 1-8	SI
266868	WELL	SI	11/01/2007	CBM	045-09186	SOUTH SHALE RIDGE 1-8H	SI

General Comment:**COGCC Inspection Report Summary**

On 3/13/2023 at approximately 12:15, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE at Location ID #334269 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Weeds on location have encroached on all production equipment
- 2) Unused equipment on location
- 3) No tank battery sign
- 4) Wellhead signs and tank labels contain inaccurate information
- 5) Weeds have compromised permeability of tank battery berms
- 6) No vehicle tracking BMP to prevent sediment migration

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Inaccurate information on wellhead signs		
Corrective Action:	Install sign to comply with Rule 605.d	Date:	04/13/2023
Type	TANK LABELS/PLACARDS		
Comment:	Inaccurate information on tank labels/placards		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	04/13/2023
Type	BATTERY		
Comment:	No tank battery sign		
Corrective Action:	Install sign to comply with Rule 605.e	Date:	04/13/2023

Emergency Contact Number:

Comment: 911/(970) 858-8550

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location		
Corrective Action:	Remove unused equipment	Date:	03/28/2023
Type	WEEDS		
Comment:	Weeds have encroached entire production area		
Corrective Action:	Remove weeds from location	Date:	03/20/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1)			Date: 04/02/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1)			Date: 04/02/2023

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected FacilitiesFacility ID: 210984 Type: WELL API Number: 045-06742 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last produced April 2010. Last MIT performed September 2021.

Corrective Action: _____ Date: _____

Facility ID: 266868 Type: WELL API Number: 045-09186 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last produced December 2009. Last MIT performed September 2021.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Inadequate tracking BMP
Sediment Traps						
		Other	Fail			Inadequate tracking BMP
		Compaction	Fail			
		Gravel	Fail			

Comment: [Location and lease road lack stabilization with no BMP in place to prevent sediment migration](#)

Corrective Action: [Comply with Rule 1002](#)

Date: 03/20/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300181	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6048994