

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2194 From entrance to location



Photo # 2195 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2196 Location



Photo # 2197 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2198 Location



Photo # 2202 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2201 Chemical BMP not maintained



Photo # 2203 Chemical BMP not maintained

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2209 Chemical BMP not maintained




Photo # 2213 Improperly marked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2219 Unmarked deadman



Photo # 2324 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2325 Meter calibration info not conspicuously posted



Photo # 2326 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2327 Meter calibration info not conspicuously posted



Photo # 2223 Culvert needs maintenance – 160 ft west of location on spur road