

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2023

Submitted Date:

03/14/2023

Document Number:

706700359**FIELD INSPECTION FORM**Loc ID 303376 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                            | Comment |
|------------------|--------------|----------------------------------|---------|
| Krehmeyer, James | 970-332-3585 | james.krehmeyer@ownresources.com |         |
| Dolezal, Pat     | 970-332-3585 | pat.dolezal@ownresources.com     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 253009      | WELL | PR     | 05/17/1983  | GW         | 125-06886 | PAPPENHEIM 2-7 | PR          |

**General Comment:**

Routine Field Inspection

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: 970-332-3585

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

|                            |                                |       |                 |
|----------------------------|--------------------------------|-------|-----------------|
| <b>Equipment:</b>          |                                |       | corrective date |
| Type: Bradenhead           | # 1                            |       |                 |
| Comment:                   |                                |       |                 |
| Corrective Action:         |                                | Date: |                 |
| Type: Horizontal Separator | # 1                            |       |                 |
| Comment:                   |                                |       |                 |
| Corrective Action:         |                                | Date: |                 |
| Type: Vertical Separator   | # 1                            |       |                 |
| Comment:                   |                                |       |                 |
| Corrective Action:         |                                | Date: |                 |
| Type: Gas Meter Run        | # 1                            |       |                 |
| Comment:                   | digital, 10/7/2022 calibration |       |                 |
| Corrective Action:         |                                | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|          |  |  |
|----------|--|--|
| Type     |  |  |
| Comment: |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: snow covered

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: dry

Corrective Action

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description        | URL   |
|--------------|--------------------|---|
| 706700385    | OWN Pappenheim 2-7 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6050066">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6050066</a> |