


**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**



From entrance to location



Access road entrance to location

**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**



Debris, wire screen repair



Chemical containment full of liquid



Caerus Piceance LLC
Love Ranch Fee 5
Location #316250



Cellar covers not maintained.



Cellar covers need to fit properly



Caerus Piceance LLC
Love Ranch Fee 5
Location #316250



Public road used to access location needs replaced.



Unmarked guy line anchor.

**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**




Erosion from upper lease road



Erosion from upper lease road

**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**



Sediment migration on to location



To entrance to location

**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**



Stormwater BMPs not in place and maintained



Stormwater BMPs not in place and maintained

**Caerus Piceance LLC
Love Ranch Fee 5
Location #316250**



Location lacks stabilization.



Insufficient tracking BMP at entrance to location.