

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2228 From entrance to location



Photo # 2229 From entrance to location

Location ID: 335494




Photo # 2230 Location




Photo # 2231 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2232 Location




Photo # 2233 Unused equipment



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2235 Chemical BMP not maintained



Photo # 2239 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2240 Unmarked deadman



Photo # 2241 Unmarked deadman



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2242 Stained soil & gravel



Photo # 2243 Stained soil & gravel



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2244 Stained soil & gravel



Photo # 2255 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2266 Unused equipment



Photo # 2331 Calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Mar 13, 2023 at 2:51:24 PM
CO



Mar 13, 2023 at 12:53:22 PM
CO

Photo # 2332 Calibration info not conspicuously posted

Photo # 2245 Vehicle tracking/No tracking BMP

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2246 Lack of stabilization



Photo # 2248 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2249 Lack of stabilization



Photo # 2250 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2251 Lack of stabilization



Photo # 2252 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2226 Culvert needs maintenance – Culvert on access road, 40 ft east of RWF 22-29 pad



Photo # 2227 Culvert needs maintenance – Culvert on access road, 180 ft east of RWF 22-29 pad