

Interim Reclamation and Stormwater Inspection

March 9, 2023

Operator: CONFLUENCE DJ LLC #10518

Location ID: 442024

Inspection Document #: 697504555

Weld County, CO

SESW Section 18 T4N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Middlepark/18
Location ID: 442024



Photo 1. Photo taken from the northeastern location, facing East. Photo illustrates the Operator is storing unused equipment.



Photo 2. Photo taken from the northern location, west of the access road, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: Middlepark/18
Location ID: 442024



Photo 3. Photo taken from the western location, facing South. Photo illustrates weed establishment and weed maintenance needed along the western fill slope.



Photo 4. Photo taken from the southwestern location, facing South. Photo illustrates both the establishment of desirable vegetation and weeds- see Photo 5.

Inspection Photos
Location Name: Middlepark/18
Location ID: 442024



Photo 5. Close up photo illustrating desirable vegetation- Blue grama.



Photo 6. Photo taken from the topsoil stockpile, facing East. Photo illustrates bare ground and wind erosion with the establishment of weeds.

CDPHE is addressing this observation.

Inspection Photos
Location Name: Middlepark/18
Location ID: 442024



Photo 7. Photo taken from the southeastern location, facing North. Photo illustrates the cut slope has not been stabilized and wind erosion is evident- see Photo 8.

CDPHE is addressing this observation.




Photo 8. Photo taken from the eastern cut slope illustrates the soil loss due to wind erosion. Sand sagebrush roots are exposed and about 1-1.5' of soil loss.

Inspection Photos
Location Name: Middlepark/18
Location ID: 442024



Photo 9. Photo taken from the eastern location, facing North. Photo illustrates weed establishment and weed maintenance needed along the eastern perimeter/cut slope.



Photo 10. Photo taken from one of the wellheads, facing East. Photo illustrates oily stained soil.

CDPHE is addressing this observation.