

Interim Reclamation and Stormwater Inspection

March 9, 2023

Operator: CONFLUENCE DJ LLC #10518

Location ID: 458676

Inspection Document #: 697504563

Weld County, CO

SWNW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 1. Photo taken from the southwestern location, facing East. Photo illustrates weed establishment and weed maintenance needed.



Photo 2. Photo taken from the topsoil stockpile, facing North. Photo illustrates bare ground with the establishment of weeds.

CDPHE is addressing this observation.

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 3. Photo taken from the western location, facing North. See comments under Photo 1 regarding weeds.



Photo 4. Photo taken from the western location, facing Northeast. Photo illustrates BMPs have not been maintained.

CDPHE is addressing this observation.

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 5. Photo taken from the northern location, facing East. Photo illustrates BMPs have not been maintained.

CDPHE is addressing this observation.



Photo 6. Photo taken from the northern location, facing East. Photo illustrates what appears to be a fill slope failure resulting in sediment discharge off location. See Photo 7.

CDPHE is addressing this observation.

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 7. Photo taken from the northern location, on top of the fill slope, facing Northwest. Photo illustrates sediment discharge beyond the ditch BMP.

CDPHE is addressing this observation.



Photo 8. Photo taken from the northern location, facing East. See comments under Photo 1 regarding weeds.

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 9. Photo taken from the northeastern location, facing East. Photo illustrates gully erosion along the ditch and berm BMP and weed establishment.

CDPHE is addressing this observation.



Photo 10. Photo taken from the northeastern location, facing South. Photo illustrates sediment has accumulated in the ditch/rip rap BMP.

CDPHE is addressing this observation.

Inspection Photos
Location Name: Silverton/4 North
Location ID: 458676



Photo 11. Photo taken from the produced water load out within secondary containment. Photo illustrates the hose has been left connected and is a potential safety concern with regards to a potential spill.

Note- Operator did disconnect hose during this inspection.



Photo 12. Photo taken from the southern location, facing East. See comments under Photo 1 regarding weeds.