

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2023

Submitted Date:

03/15/2023

Document Number:

702801345

FIELD INSPECTION FORM

Loc ID: 334899 Inspector Name: O'Malley, Anna On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerusoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264145	WELL	SI	08/01/2020	GW	045-08178	BENZEL 36-13A (K36B)	RI
264146	WELL	PR	11/01/2021	GW	045-08180	BENZEL 36-15B (K36B)	RI
264148	WELL	PR	06/22/2002	GW	045-08181	BENZEL 36-7C (K36B)	RI
264149	WELL	PR	04/07/2003	GW	045-08182	BENZEL 36-12A (K36B)	RI
334899	LOCATION	AC			-	BENZEL-66S93W 36NESW	RI

General Comment:

On 3/14/2023, Reclamation Specialist O'Malley conducted a reclamation inspection at Caerus Piceance LLC's BENZEL-66S93W/36NESW Location #334899 in Garfield County, Colorado.

This is a follow up to inspection document #702801224.

The following compliance issues were observed during this inspection:

- Tank spilled, staining in secondary containment
- Trash
- Bull plug not installed

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash observed on location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	03/22/2023
Type	OTHER		
Comment:	A produced water/condensate tank appears to have spilled from the top. Staining was observed down the side of the tank and stained gravel was observed within secondary containment below the spill.		
Corrective Action:	Remove and properly dispose of stained materials.	Date:	03/30/2023

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Type: Flow Line				
Comment:	Corrective action to remove riser equipment associated with plugged and abandoned well from inspection document #702801224 has been addressed. Corrective action is no longer applicable.			
Corrective Action:			Date:	
Type: Other				
Comment:	Bull plug not installed on tank drain line.			
Corrective Action:	Install bull plug on tank drain line.		Date:	03/25/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 264145 Type: WELL API Number: 045-08178 Status: SI Insp. Status: RI

Facility ID: 264146 Type: WELL API Number: 045-08180 Status: PR Insp. Status: RI

Facility ID: 264148 Type: WELL API Number: 045-08181 Status: PR Insp. Status: RI

Facility ID: 264149 Type: WELL API Number: 045-08182 Status: PR Insp. Status: RI

Facility ID: 334899 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues observed at the time of this inspection. There is some subsidence occurring at the backfilled trench where a flowline was removed.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801356	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6051477