

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2334 From entrance to location



Photo # 2335 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2337 Location



Photo # 2338 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2339 Location



Photo # 2344 Calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2345 Calibration info not conspicuously posted



Photo # 2346 Calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2348 Calibration info not conspicuously posted



Photo # 2340 Weeds/Undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2343 Weeds/Undesirable plant species



Photo # 2340 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2350 Lack of stabilization



Photo # 2351 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2352 Lack of stabilization



Photo # 2353 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2354 Lack of stabilization



Photo # 2355 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2356 Lack of stabilization



Photo # 2357 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2358 Lack of stabilization/Tracking onto lease road



Photo # 2359 Tracking onto lease road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 13-30 pad

Location ID: 335503



Photo # 2362 Tracking on lease road



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources