

Inspection Photos  
Location Name: Anderson Trust 1  
Location ID: 318607



Photo 1 WH sign.

Photo 2 WH possible leak, ground is saturated in outline.

**Inspection Photos**  
**Location Name: Anderson Trust 1**  
**Location ID: 318607**



**Photo 3 possible leak from threads on WH.**

**Photo 4 stained ground**

**Inspection Photos**  
**Location Name: Anderson Trust 1**  
**Location ID: 318607**



**Photo 5 Pump jack.**

**Photo 6 Prime mover (gas engine)**

**Inspection Photos**  
**Location Name: Anderson Trust 1**  
**Location ID: 318607**



**Photo 7 wellsite.**

**Photo 8 Auxiliary tank no spill containment.**

**Inspection Photos**  
**Location Name: Anderson Trust 1**  
**Location ID: 318607**



**Photo 9 Aux. tank has no labels or markers to indicate volume or contents, no spill containment.**

**Photo 10 Auxiliary tank valves leaking no spill containment.**

Inspection Photos  
Location Name: Anderson Trust 1  
Location ID: 318607



Photo 11 TB Sign.

Photo 12 TB.

Inspection Photos  
Location Name: Anderson Trust 1  
Location ID: 318607



Photo 11 TB Sign.

Photo 12 TB.