

# Inspection Photos

API: 025-06021

Operator: VAL ENERGY INC

Inspection Date: 3/14/2023




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023

## Inspection Photos



**Photo 1.** Center of the location facing north. The perennial vegetation has not yet established to 80% of reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023



## Inspection Photos



**Photo 2.** Center of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023



## Inspection Photos



**Photo 3.** Center of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023



## Inspection Photos



**Photo 4.** Center of the location facing west.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023

## Inspection Photos



**Photo 5.** North side of the location facing west. The northern portion of the location is mostly devoid of vegetation and needs to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023



## Inspection Photos



**Photo 6.** Drone aerial photo facing north toward the location. The northern portion of the disturbed location at red arrow is mostly bare soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023



## Inspection Photos



**Photo 7.** Drone aerial image facing west at the surrounding undisturbed uniform vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06021 | Date: 3/14/2023