

TEP  
Miller 10  
Location # 423439



Location and inspector did not drive onto location  
due to muddy conditions



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

TEP  
Miller 10  
Location # 423439



**Lack of stabilization/compaction/no evidence of tracking BMP's**



**Lack of stabilization/compaction/no evidence of tracking BMP's**

TEP  
Miller 10  
Location # 423439



**Lack of stabilization/compaction/no evidence of tracking BMP's**



**Lack of stabilization/compaction/no evidence of tracking BMP's**



TEP  
Miller 10  
Location # 423439



**Lack of stabilization/compaction/no evidence of tracking BMP's**



**Lack of stabilization/compaction/no evidence of tracking BMP's**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

TEP  
Miller 10  
Location # 423439




**Lack of stabilization/compaction/no evidence of tracking BMP's**



**Lack of stabilization/compaction/no evidence of tracking BMP's**



TEP  
Miller 10  
Location # 423439



Debris



Debris

