

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2023

Submitted Date:

03/16/2023

Document Number:

707800227

**FIELD INSPECTION FORM**

Loc ID 383325	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 19 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301714	WELL	PR	06/15/2010	GW	045-18233	GGU MILLER 33B-31-691	PR
301715	WELL	PR	06/28/2010	GW	045-18234	GGU MILLER 33A-31-691	PR
301716	WELL	PR	06/28/2010	GW	045-18235	GGU MILLER 34B-31-691	PR
301717	WELL	PR	06/28/2010	GW	045-18236	GGU MILLER 34C-31-691	PR
301718	WELL	PR	06/28/2010	GW	045-18237	GGU MILLER 34A-31-691	PR
301719	WELL	PR	06/28/2010	GW	045-18238	GGU MILLER 34D-31-691	PR
301721	WELL	PR	06/15/2010	GW	045-18239	GGU MILLER 33C-31-691	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Wednesday 3/15/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Miller 6, at Location # 383325 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (stored equipment) has not been addressed from previous inspection document # 700703643. All other C/A's appear to have been addressed.  
 During this inspection the following compliance issues were observed:

1. Meter calibration card not conspicuously posted.
2. Stored/unused equipment from previous inspection is still present. C/A date remains the same (3/8/2022)
3. Tank missing information
4. Chemical tank containment is full of fluid.
5. Paraffin and hydrocarbon sheen on water in tank containment.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank missing information		
Corrective Action:	Provide proper labeling	Date:	03/31/2023
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Paraffin and hydrocarbon sheen on water in tank containment.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Stored/unused equipment from previous inspection is still present. C/A date remains the same (3/8/2022)		
Corrective Action:	Remove stored/unused equipment	Date:	03/08/2022
Type	OTHER		
Comment:	Chemical tank containment is full of fluid.		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date:	03/31/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	See stored equipment for C/A		
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:	Meter calibration card not conspicuously posted.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration.		Date: 04/05/2023
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	HEATED STEEL AST		,	
Comment:	1 tank is not heated					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	10	OTHER	HEATED STEEL AST		,	

Comment:	2 tanks are not heated		
Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	301714	Type:	WELL	API Number:	045-18233	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301715	Type:	WELL	API Number:	045-18234	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301716	Type:	WELL	API Number:	045-18235	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301717	Type:	WELL	API Number:	045-18236	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301718	Type:	WELL	API Number:	045-18237	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301719	Type:	WELL	API Number:	045-18238	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	301721	Type:	WELL	API Number:	045-18239	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Ditches				
		Sediment Traps				
		Rip Rap				
Rip Rap						
		Culverts				

Comment: [Limited storm water inspection due to snow cover and water pooling](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800232	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052471">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052471</a>