

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2023

Submitted Date:

03/16/2023

Document Number:

702801360

**FIELD INSPECTION FORM**

Loc ID: 334602      Inspector Name: O'Malley, Anna      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER      State: CO      Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerusoilandgas.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263849	WELL	PR	03/18/2005	GW	045-08146	CEDAR SPRINGS RANCH 11-11	RI
271508	WELL	PR	04/01/2005	GW	045-09892	CEDAR SPRINGS RANCH 11-7D(J11W)	RI
271940	WELL	PR	05/07/2013	GW	045-09980	CEDAR SPRINGS RANCH 11-11C (J11W)	RI
271941	WELL	PR	03/03/2005	GW	045-09981	CEDAR SPRINGS RANCH 11-10D (J11W)	RI
271967	WELL	PR	04/09/2005	GW	045-09978	CEDAR SPRINGS RANCH 11-11D (J11W)	RI
334602	LOCATION	AC			-	CEDAR SPRINGS RANCH-67S93W 11NWSE	RI

**General Comment:**

On 3/14/2023, Reclamation Specialist O'Malley conducted a reclamation inspection at Caerus Piceance LLC's CEDAR SPRINGS RANCH-67S93W/11NWSE Location #334602 in Garfield County, Colorado.

This is a follow up to inspection document #702801264 to document compliance with corrective actions.

The following compliance issues were observed during this inspection:  
 - Tank spilled, staining in secondary containment

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			
Comment:	Previous inspection #702801264 observed produced water/condensate tank #81396 appears to have spilled from the top. Staining was observed. Inspector required Operator to remove stained materials and document integrity of containment structure. Properly dispose of oily waste in accordance with 905.e by 3/2/2023. Operator submitted FIRR #403326721 indicating "cleaned".  It was observed in this inspection that stained material is present within the tank battery secondary containment; stained gravel and snow were observed below the spilled tank. Operator has not documented the integrity of the containment structure. Original corrective action and date remain applicable.				
Corrective Action:	Remove stained materials and document integrity of containment structure. Properly dispose of oily waste in accordance with 905.e.			Date:	03/02/2023

In Containment: Yes \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: <u>263849</u>	Type: <u>WELL</u>	API Number: <u>045-08146</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271508</u>	Type: <u>WELL</u>	API Number: <u>045-09892</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271940</u>	Type: <u>WELL</u>	API Number: <u>045-09980</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271941</u>	Type: <u>WELL</u>	API Number: <u>045-09981</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271967</u>	Type: <u>WELL</u>	API Number: <u>045-09978</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>334602</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801361	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052671">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052671</a>