

Interim Reclamation and Stormwater Inspection

Date: 03/15/2023

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 430662

Inspection Document #: 708200034

Weld County, CO

SWSW Section 23 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 1. Facing south within secondary containment of battery. Oily waste/stained soil observed around barrel was identified in previous inspection (Doc #696105742) and has not been addressed. The corrective action is being back-dated to when it should have been addressed (see attached report for details).

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 2. Facing north from interim area. Red outline illustrates location of previously stockpiled, impacted material. It appears the Operator has removed the impacted material off location.



Photo 3. Close up photo of oil stained soil that was near the stockpile material mentioned in Photo 2. This stained soil will need to be properly cleaned up and disposed of per Rule 905.e.

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photos 4 & 5. It appears the Operator has cleaned up the piping, checked equipment, and removed stained soil as identified in previous corrective actions.

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 6. Appears operator has performed the previous corrective actions and removed the tumbleweed accumulations from equipment.



Photo 7. Facing east from the southern portion of the interim area. It appears the operator has performed interim reclamation activities. However, the interim areas are predominantly undesirable vegetation (e.g. russian thistle and kochia) with areas of non-uniform vegetation cover resulting in bare soil. Note: some desirable species were also observed during this inspection (e.g. sand drop seed).

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 8. Facing north from the eastern portion of the interim area; see comments in Photo 7.

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 9. Facing west from the northern portion of the interim area; see comments in Photo 7.

Inspection Photos
Location Name: Waves 1H
Location ID: 430662



Photo 10. Facing east from the northwestern portion of the interim area; see comments in Photo 7.