

Interim Reclamation and Stormwater Inspection

Date: 03/15/2023

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 428225

Inspection Document #: 708200049

Weld County, CO

NWSW Section 5 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 1. Facing southeast from the entrance to the location. Photo illustrates that it appears that interim reclamation activities have been performed, however, portions of the interim areas have failed to revegetate resulting in bare soil, or undesirable vegetation (e.g. kochia and russian thistle) was observed at the time of this inspection.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 2. Facing east from the southern interim area; see comments in Photo 1.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 3. Closeup of interim area; see comments in Photo 1.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 4. Facing north from the eastern portion of interim area; see comments in Photo 1.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 5. Facing west from the northern portion of the interim areas; predominantly undesirable species with some desirable species mixed throughout.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 6. Facing south from southeastern portion of interim area. Trash will need to be properly disposed of.

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 7. Facing southwest near battery. Road drag/maintainer observed being stored on location. This will need to be removed as equipment cannot be stored on location.