

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



Photo # 2538 From entrance to location



Photo # 2539 From entrance to location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



Photo # 2540 From entrance to location



Photo # 2541 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



Photo # 2542 Location



Photo # 2543 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



Photo # 2546 Debris



Photo # 2548 Calibration info not conspicuously posted



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2549 Gulley erosion into ditch (SE corner of location near road)**



**Photo # 2550 Ditch needs maintenance (SE corner of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



Photo # 2551 Ditch needs maintenance (S/SE side of location)



Photo # 2553 Rip Rap needs maintenance (SW corner of location)



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2554 Rip Rap needs maintenance (SW corner of location)**



**Photo # 2555 Rip Rap needs maintenance (SW corner of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2556 Insufficient runoff controls/BMP's – Channel erosion (SW corner of location)**



**Photo # 2557 Insufficient runoff controls/BMP's – Channel erosion (off SW corner of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2559 Insufficient runoff controls/BMP's – Channel erosion (off SW corner of location)**



**Photo # 2560 Insufficient runoff controls/BMP's – Channel erosion & berm needs maintenance (off SW corner of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2561 Berm needs maintenance (Berm is off SW corner of location)**



**Photo # 2562 Insufficient runoff controls/BMP's – Channel erosion (below berm off SW corner of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2564 Ditch needs maintenance (Access road)**



**Photo # 2565 Sediment Trap needs maintenance (N side of location off access road)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 31-2 Pad

Location ID: 323884



**Photo # 2567 Sediment Trap needs maintenance (N side of location off access road)**



**Photo # 2569 Sediment Trap needs maintenance (N side of location off access road)**