

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2023

Submitted Date:

03/10/2023

Document Number:

696304712

FIELD INSPECTION FORM

Loc ID 431925 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431922	WELL	PR	07/01/2021	OW	123-36864	Nelson 5-17-9-60	PR
431923	WELL	SI	02/01/2022	OW	123-36865	Nelson 3-17-9-60	TA
431927	WELL	PR	06/01/2022	OW	123-36868	Nelson 2-17-9-60	PR
431928	WELL	PR	06/01/2022	OW	123-36869	Nelson 4-17-9-60	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained Soil at North West Load Line Bucket and South Heater Treaters. See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	03/31/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused Pumping Unit at 3-17-9-60 (Well appears to have been Plugged and Abandoned)		
Corrective Action:	Comply with Rule 606	Date:	05/12/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			
Type: Emission Control Device	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 3		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Field Flare		
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 431922 Type: WELL API Number: 123-36864 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: 431923 Type: WELL API Number: 123-36865 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to have been Plugged and Abandoned per Form 42 PA - 403056438 dated 05.23.2022 and Form 6S 403072507 dated 06-08-2022 STILL In-Process

Corrective Action: _____ Date: _____

Facility ID: 431927 Type: WELL API Number: 123-36868 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: 431928 Type: WELL API Number: 123-36869 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Unused Pumping Unit at North End of Wells - 3-17-9-60 appears to have been Plugged and Abandoned - Unit no longer in use. Stained Soil at NW Loadline Bucket and South Heater Treaters	petrie	03/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403342997	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046647
696304713	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046645