

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2023

Submitted Date:

03/10/2023

Document Number:

708300172

FIELD INSPECTION FORMLoc ID 335480 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293606	WELL	PR	10/23/2012	GW	045-15061	CASCADE CREEK 797-06-05A	PR
293608	WELL	PR	10/23/2012	GW	045-15063	CASCADE CREEK 797-06-07	PR

General Comment:**COGCC Inspection Report Summary**

On 3/9/2023 at approximately 10:30, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, CC/0797-06-07 Pad at Location ID #335480 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Damaged berm wall at tank battery
- 2) Location lacks stabilization with inadequate tracking BMP
- 3) Unprotected soil stockpiles on location
- 4) Slope north of production pad is eroding and encroaching production equipment
- 5) Gas meter calibration record not conspicuously displayed

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 2		
Comment:	Calibration record not conspicuously displayed		
Corrective Action:	Display legible meter calibration record in conspicuous location		Date: 03/20/2023
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		

Comment:	Out of service		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 2			
Comment:	Both wells on plunger lift		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Berm wall and lining damaged			
Corrective Action:	Repair berm wall and liner			Date: 04/10/2023

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293606	Type:	WELL	API Number:	045-15061	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293608	Type:	WELL	API Number:	045-15063	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Slope eroding and encroaching production equipment
		Ditches				
		Culverts				
		Compaction	Fail			Lease road lacks stabilization
		Berms				
Other	Fail					Inadequate tracking BMP
		Other	Fail			Inadequate tracking BMP
Ditches						
		Gravel	Fail			Lease road lacks stabilization
Gravel	Fail					Location lacks stabilization
Berms						
Compaction	Fail					Location lacks stabilization

Comment: 1) Slope north of production pad is eroding and encroaching production equipment
 2) Unprotected soil stockpiles on location
 3) Location lacks stabilization and has inadequate tracking BMP in place to prevent sediment migration

Corrective Action: **Comply with Rule 1002 for erosion control, soil stockpiles, and tracking controls**

Date: 03/17/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403343168	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046845
708300174	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046839