

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2364 From entrance to location



Photo # 2365 From entrance to location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2366 Location



Photo # 2367 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2368 Location



Photo # 2369 Calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2370 Calibration info not conspicuously posted



Photo # 2371 Calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2372 Debris - Barbed wire laying on ground/wildlife hazard



Photo # 2373 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2374 Containment needs maintenance



Photo # 2375 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2376 Containment needs maintenance



Photo # 2377 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2400 Gulley erosion off edge of pad



Photo # 2401 Gulley erosion off edge of pad

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2405 Gulley erosion off edge of pad



Photo # 2404 Gulley erosion off edge of pad

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Mar 14, 2023 at 1:02:23 PM



Mar 14, 2023 at 1:02:40 PM

Photo # 2390 Lack of stabilization

Photo # 2391 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2392 Lack of stabilization



Photo # 2393 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2394 Lack of stabilization



Photo # 2395 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2406 Lack of stabilization



Photo # 2407 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2408 Lack of stabilization



Photo # 2409 Insufficient tracking BMP/Vehicle Tracking onto lease road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2413 Insufficient tracking BMP/Tracking onto County Road 309



Photo # 2414 Insufficient tracking BMP/Tracking onto County Road 309

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2412 Insufficient tracking BMP/Tracking onto County Road 309



Photo # 2392 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2396 Failure to minimize surface disturbance



Photo # 2397 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 2398 Failure to minimize surface disturbance