

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2023

Submitted Date:

03/15/2023

Document Number:

699504482

FIELD INSPECTION FORMLoc ID 317802 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239996	WELL	PR	03/20/1995	OW	123-07784	DAVID HOWARD B-1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Gas meter run valves appeared to be open, and automation equipment showed flow/sales activity. Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863		
Corrective Action:	Comply with Order 1v-863	Date:	02/22/2023
Type	OTHER		
Comment:	stained soil, and trash needs to be removed from multiple spots on location, see pics		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	04/15/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	6' chain link with barb wire.		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Fluid pumps		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,	
Comment:	60 BBL					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		shares containment with oil tank					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	4	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 239996 Type: WELL API Number: 123-07784 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/02/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Annual bradenhead test is not current, Contact COGCC engineering.03/25/2023Corrective Action: Comply with COGCC annual bradenhead testing rules

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 3/15/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- David Howard B-1</p> <p>Company Name- KPK</p> <p>API- 05-123-07784</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well</p> <p>This is a follow up inspection from document # 699504427 Corrective Actions are Delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>stained soil, and trash needs to be removed from multiple spots on location, see pics</p> <p>Comply with COGCC housekeeping rules 4/15/23</p> <p>Gas meter run valves appeared to be open, and automation equipment showed flow/sales activity.</p> <p>Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863</p> <p>Comply with Order 1v-863 2/22/23</p> <p>Annual bradenhead test is not current Contact COGCC engineering</p> <p>Comply with COGCC annual bradenhead testing rules. 3/25/22</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This inspection does not nullify any orders, corrective actions, or NOAV from the COGCC.</p> <p>At time of inspection weather conditions were warm, overcast, light wind.</p> <p>This is a summary of inspection report.</p>	medinaj	03/15/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699504483	inspection pictures	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6056646