

Caerus Piceance LLC
Nolte 14-796
Location #435806



Sign at access road entrance off I70 frontage road

Middle of location looking North

**Caerus Piceance LLC
Nolte 14-796
Location #435806**



Middle of location looking Northwest



Middle of location looking West

**Caerus Piceance LLC
Nolte 14-796
Location #435806**



Unused equipment inside Dehy containment



Debris on Dehy skid

Caerus Piceance LLC
Nolte 14-796
Location #435806



Open end loadline



Unused equipment inside tank battery

**Caerus Piceance LLC
Nolte 14-796
Location #435806**



Unused equipment. Containment open to wildlife.



Debris. Open end tank valve.

**Caerus Piceance LLC
Nolte 14-796
Location #435806**



Debris. Open end tank valve.



Debris. Open end tank valve.

Caerus Piceance LLC
Nolte 14-796
Location #435806



Debris inside tank containment



Debris inside tank containment

**Caerus Piceance LLC
Nolte 14-796
Location #435806**




Peeled label. Lacking Name of Operator and Operator emergency contact information.




Peeled label. Lacking Name of Operator and Operator emergency contact information.

Caerus Piceance LLC
Nolte 14-796
Location #435806



**Peeled label. Lacking Name of Operator and
Operator emergency contact information.**

Caerus Piceance LLC
Nolte 14-796
Location #435806



Containment pulled from anchor post



Liner pulled apart inside of containment

Caerus Piceance LLC
Nolte 14-796
Location #435806



Debris outside tank containment



Debris at wellhead

**Caerus Piceance LLC
Nolte 14-796
Location #435806**



Debris at wellhead



Debris at wellhead

Caerus Piceance LLC
Nolte 14-796
Location #435806



Condensate or Produced Water? Conflicting labels



Debris inside tank containment

Caerus Piceance LLC
Nolte 14-796
Location #435806



Debris at filter skid.



Debris at filter skid.