

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2023

Submitted Date:

03/21/2023

Document Number:

705000212

FIELD INSPECTION FORMLoc ID 305702 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281281	WELL	SI	10/01/2021	GW	123-23374	EWERTZ 3-18	PA
305702	LOCATION	AC			-	EWERTZ-62N65W 18NENW	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 281281 Type: WELL API Number: 123-23374 Status: SI Insp. Status: PAFacility ID: 305702 Type: LOCATION API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Ewertz 3-18) has been plugged and abandoned; cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #403240451 received 11/28/2022. COGCC form 42 flowline notice of flowline abandonment completed doc #403350145 received 03/20/2023. Fenced excavations were observed at the PA wellhead and facility/ equipment areas. OLF wellhead flowline has been removed. No flowline risers observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. Contract personnel were on location at the time of inspection; excavation work is in progress.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000214	PA well and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057563
705000215	View of location to east; OOS GMR's	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057564