

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2023

Submitted Date:

03/21/2023

Document Number:

705000213

**FIELD INSPECTION FORM**

Loc ID 318062 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275621	WELL	TA		OW	123-22649	WARNER 5-18	TA
442128	TANK BATTERY	CL	06/17/2015		-	WARNER TANK BATTERY 33-18	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 275621 Type: WELL API Number: 123-22649 Status: TA Insp. Status: TA

Facility ID: 442128 Type: TANK API Number: - Status: CL Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: The facility/ tank battery has been decommissioned; tanks and equipment have been removed. On location dump and process flowlines have been removed. Wells serviced by this facility prior to decommissioning are TA; off location flowlines have been removed/ AIP. Fenced excavations observed at battery/ equipment areas. No flowlines or flowline risers were observed within excavation areas on location. Remediation work at facility/ battery is in progress (historical).

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">As outlined on COGCC form 19 spill report Doc #403342579 received on 03/10/2023: On March 10, 2023, historical soil impacts were discovered following flowline removal operations at the Warner 5-18 flowline location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.</span>	maclarej	03/21/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000216	View of excavation areas on location; to N	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057917</a>
705000217	View of location and fenced excavations; to S	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6057918</a>