

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2745 From entrance to location



Photo # 2746 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2747 Location



Photo # 2748 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2749 Location



Photo # 2750 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2755 Undesirable plant species




Photo # 2756 Undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2758 Containment liner needs maintenance



Photo # 2759 Containment liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2761 Culvert needs maintenance (Culvert is near entrance to location)



Photo # 2762 Gully erosion at culvert insufficient BMP's (Culvert is near entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Mar 21, 2023 at 12:46:27 PM
CO

Photo # 2763 – Rill erosion/ditch needs maintenance



Mar 21, 2023 at 12:46:36 PM
CO

Photo # 2764 Rill erosion/ditch needs maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2767 Rill erosion/transport of sediment off location



Photo # 2768 Rill erosion

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2770 Rill erosion & transport of sediment off location (south side of location)



Photo # 2771 Rill erosion (south side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # Degradation of roadway/insufficient BMP's (east side of location)



Photo # 2774 Ditch needs maintenance (E/SE side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Mar 21, 2023 at 12:51:52 PM
CO

Photo # 2776 Ditch needs maintenance (E/SE side of location)



Mar 21, 2023 at 12:52:07 PM
CO

Photo # 2777 Ditch needs maintenance (E/SE side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2778 Ditch needs maintenance (E/SE side of location)



Photo # 2780 Berm needs maintenance/sediment encroaching on & choking off vegetation (S/SE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2781 Berm needs maintenance/sediment encroaching on & choking off vegetation (S/SE area of location)



Photo # 2782 Berm needs maintenance/sediment encroaching on & choking off vegetation(S/SE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2784 Berm needs maintenance/sediment encroaching on & choking off vegetation (S/SE area of location)



Photo # 2786 Berm needs maintenance/sediment encroaching on & choking off vegetation (S/SE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2787 Sediment encroaching on & choking off vegetation (S/SE area of location)



Photo # 2796 Sediment encroaching on & choking off vegetation

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2792 Rill erosion & transport of sediment off location (South side of location)



Photo # 2793 Transport of sediment off location/encroaching on & choking off vegetation (south side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Mar 21, 2023 at 12:51:35 PM
CO



Mar 21, 2023 at 12:54:25 PM
CO

Photo # 2775 Lack of stabilization

Photo # 2788 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2789 Lack of stabilization



Photo # 2795 Lack of stabilization



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 533-22 pad

Location ID: 335367



Photo # 2797 Lack of stabilization