

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2023

Submitted Date:

03/22/2023

Document Number:

696304726**FIELD INSPECTION FORM**Loc ID 426841 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426812	WELL	SI	08/01/2017	OW	123-34787	Wolf 36-3624H	SI

General Comment:

This is a Field Inspection. Any Corrective Actions from Interim Reclamation and Stormwater Inspection 696105632 dated 12.06.2022 are STILL applicable ant Corrective Actions remain the SAME.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign still shows Whiting is the Operator; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 04/24/2023
Type	OTHER		
Comment:	From Inspection 696105632, dated 12.05.2022. No emergency contact information posted; Sign not legible at treater/building. Refer to attached inspection photos.		
Corrective Action:	Install sign to comply with Rule 605.g		Date: 01/06/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank Battery Sign still shows Whiting as Operator		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 04/24/2023
Type	BATTERY		
Comment:	Sign at Entrance still shows Whiting as Operator. See photos		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 04/24/2023

Emergency Contact Number:

Comment: No Updated Fundare 24 Emergency Contact Number or Info. Posted on Site

Corrective Action: Install sign to comply with Rule 605.a.

Date: 04/24/2023

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	From Inspection 696105632 dated 12.06.2022. Unused pipe and fittings located on northwest corner of location. See photos.		
Corrective Action:	Comply with Rule 606		Date: 12/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		40.800530,-103.929040
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	426812	Type:	WELL	API Number:	123-34787	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: TA - MIT 07.30.2020									
Corrective Action: _____									
Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. All Signs on Location STILL show Whiting Oil and Gas. Unused Pipes and Fittings where ECD and Flare have been removed. Refer to I.R. and Stormwater Inspection 696105632 dated 12.06.2022 for Weeds on Location	petrie	03/22/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304727	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058832