

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 1 WH sign.

Photo 2 WH, stained soil

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 3 Ancillary equip.

Photo 4 TB sign.



Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 5 TB, Paint is faded and peeling making it hard to see the labels and placards even though they are new.

Photo 6 Horizontal Heated Separators.

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 7 ECD.

Photo 8 Flow line manifold.

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 9 Flow line.

Photo 10 Unused pipe by TB.

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 11 Unused Flow lines not LOTO and cement pad.

Photo 12 Unused flow lines not LOTO.

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 13 Compressor house.

Photo 14 inside of the compressor house.

Inspection Photos
Location Name: Dechant State #1
Location ID: 336321



Photo 15 Gas meter Run.