



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/15/2023

Submitted Date:
03/16/2023

Document Number:
707800228

FIELD INSPECTION FORM

Loc ID
383321

Inspector Name:
Ramsey, Scott

On-Site Inspection ☐

2A Doc Num:

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300520	WELL	PR	12/31/2009	GW	045-17925	GGU MILLER 14A-32-691	PR
300521	WELL	PR	11/30/2009	GW	045-17926	GGU MILLER 43A-31-691	PR
300522	WELL	PR	11/30/2009	GW	045-17927	GGU MILLER 44C-31-691	PR
300523	WELL	PR	11/30/2009	GW	045-17928	GGU MILLER 44A-31-691	PR
300524	WELL	PR	12/29/2009	GW	045-17929	GGU MILLER 14B-32-691	PR
300525	WELL	PR	12/19/2009	GW	045-17930	GGU MILLER 14C-32-691	PR
300526	WELL	PR	07/26/2010	GW	045-17931	GGU MILLER 14D-32-691	PR
300527	WELL	PR	11/25/2009	GW	045-17932	GGU MILLER 44D-31-691	PR
300528	WELL	PR	11/07/2009	GW	045-17933	MILLER 43B-6-791	PR
300529	WELL	PR	11/07/2009	GW	045-17934	MILLER 43D-6-791	PR
300530	WELL	PR	11/03/2009	GW	045-17935	MILLER 43C-6-791	PR
300531	WELL	PR	11/07/2009	GW	045-17936	MILLER 43A-6-791	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 3/15/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Miller 7, at Location # 383321 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (stored equipment) has not been addressed from previous inspection document # 700703644. All other C/A's appear to have been addressed.

During this inspection the following compliance issues were observed:

1. Meter calibration card not conspicuously posted.
2. Stored/unused equipment from previous inspection is still present. C/A date remains the same (3/8/2022)
3. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	03/24/2023
Type	STORAGE OF SUPL		
Comment:	Stored/unused equipment from previous inspection is still present. C/A date remains the same (3/8/2022)		
Corrective Action:	Remove stored/unused equipment	Date:	03/08/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 18		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 12		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	See stored equipment for C/A		
Corrective Action:			Date:
Type: Gas Meter Run	# 12		
Comment:	Meter calibration card not conspicuously posted.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration.		Date: 04/05/2023
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 18		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	7	500 BBLS	HEATED STEEL AST		,	
Comment:	3 tanks are not heated					
Corrective Action:						
Date:						

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	300520	Type:	WELL	API Number:	045-17925	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300521	Type:	WELL	API Number:	045-17926	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300522	Type:	WELL	API Number:	045-17927	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300523	Type:	WELL	API Number:	045-17928	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300524	Type:	WELL	API Number:	045-17929	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300525	Type:	WELL	API Number:	045-17930	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300526	Type:	WELL	API Number:	045-17931	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	300527	Type:	WELL	API Number:	045-17932	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	300528	Type:	WELL	API Number:	045-17933	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	300529	Type:	WELL	API Number:	045-17934	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	300530	Type:	WELL	API Number:	045-17935	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	300531	Type:	WELL	API Number:	045-17936	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Rip Rap				
		Check Dams				
		Culverts				
Gravel						
Berms						
		Sediment Traps				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403348206	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052480
707800233	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6052472