

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 3/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 1. Facing south along the main road. There is erosion occurring along the road side. BMP's need to be installed to prevent erosion. Red arrow points to 4.5' shovel. Previous corrective action not completed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 2. Facing west toward near the access road ascending the hillside. The culvert outlet has been washed out from recent storm event. It appears a larger culvert is needed along with larger rock rip/rap outlet protection. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 3. The culvert inlet is filled in with sediment and debris. It appears a larger culvert is needed at this area to handle stormwater coming off the road and drainage. Previous corrective action not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 3. The culvert inlet is filled in with sediment and debris. It appears a larger culvert is needed at this area to handle stormwater coming off the road and drainage. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 4. There are signs stormwater is flowing down the road causing erosion. This area has been a problem before and needs to be stabilized. Stormwater is not being properly diverted off the road. Additionally the road is very slick and vehicle rutting is occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 5. Facing west along the access road. Some of the rock check dams previously installed have washed out. Larger rock was likely needed. A 4.5 ft. shovel shows scale of erosion. Photo taken during previous inspection on 9/23/22.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 6. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023

Inspection Photos



Photo 7. There are still noxious weeds Hounds tongue and Canada thistle which have not been controlled. The noxious weeds have produced seed so the weeds should have been bagged and removed. Red arrow points to Hounds tongue List B noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/22/2023