

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2023

Submitted Date:

03/24/2023

Document Number:

706700455

FIELD INSPECTION FORM

Loc ID 317059 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 24500
Name of Operator: PADCO LLC
Address: 800 W 6TH STREET SUITE 1010
City: LOS ANGELES State: CA Zip: 90017

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5658	tcrumley@tcrumleypumpingsevice.com	Pumper
Richmond, Dan	(918) 630-9912	dan@dsrinc.net	Field Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
235581	WELL	PR	01/01/2023	OW	121-08071	VENRICK 1-A	SI

General Comment:

Spill Inspection (no spill number is yet generated)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	>= 5 bbls	
Comment:	Pumper contacted inspector at noon on 3/22/2023 about a 30 bbls oil spill at the Venrick 1 -A wellhead. Vac truck got 20 bbls of free oil and the spill was contained with dirt berms from around the well. Oil did not leave location and the crop field is fallow around the location. Some free oil was observed on 3/23/2023 from the dirt being bermed. Operator contacted landowner and will submit a Form 19I. See attached photos.		
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.		Date: <u>03/27/2023</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 235581 Type: WELL API Number: 121-08071 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI at time of spill. Valve on wellhead broke from the Venrick 2-A well per pumper. Pumper contacted inspector at noon on 3/22/2023 about a 30 bbls oil spill at the Venrick 1-A wellhead. Vac truck got 20 bbls of free oil and the spill was contained with dirt berms from around the well. Oil did not leave location and the crop field is fallow around the location. Some free oil was observed on 3/23/2023 from the dirt being bermed. Operator contacted landowner and will submit a Form 19I.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
706700456	PADCO Venrick 1-A spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062303