

Construction and Stormwater Inspection

Date: 03/23/2023

Operator: NAVEX RESOURCES LLC - 10360

Location ID: 483129

Inspection Document #: 708200068

Kit Carson County, CO

SENE Section 10 T11S R45W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photos 1 & 2. Facing northwest and southwest at the location entrance. Vehicle track out pad and stormwater BMPs installed. Location signage was not observed at the entrance as required by Rule 406.d.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 3. Facing northwest at the construction pad entrance. Photo illustrates that the approach to the pad, and the access road (both outlined in red), have not been salvaged for topsoil and will be required Per Rule 1002.b. Red arrow illustrates location signage that needs to be moved to the entrance for the access road.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 4. Facing east along access road. Topsoil from the access road has not been salvaged at the time of this inspection.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 5. Facing northwest from the southeast corner of the construction pad; see comments in Photos 3 & 4.



Photo 6. Facing southwest from the northeast corner of the construction. It appears temporary BMPs (surface roughening) have been installed during the initial site construction. On-site contractor advised that straw wattles would be installed at a later date. Some BMPs are still in-process (sediment traps, etc). More permanent stormwater BMPs should be selected after pad construction is completed. Topsoil stockpiles also pictured on the interior perimeter of the disturbance area.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 7. Facing southeast from the northwest corner; see comments in Photo 6.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 8. Facing northeast from the southwest corner of the location, near the proposed sediment trap location. See comments in Photo 6.



Photo 9. Facing east at the southern topsoil stockpile. Appears the topsoil has been segregated and stockpiled and will need to be stabilized from wind and water erosion. Construction was still on going during this inspection; a follow-up inspection will be conducted to document the topsoil stockpiles for Rule 1002.c compliance.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 10. Facing west from the proposed well location; photo illustrates topsoil salvage with rule for scale.



Photo 11. Facing southeast from the northern portion of the location. It appears that topsoil has been salvaged from the location in accordance with Rule 1002.b.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 12. Facing south from the northern part of the location; see comments in Photo 11.