

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



Photo # 2802 From entrance to location



Photo # 2803 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



Photo # 2804 Location



Photo # 2805 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



Mar 22, 2023 at 12:45:04 PM  
CO



Mar 22, 2023 at 12:45:57 PM  
CO

Photo # 2806 Location

Photo # 2807 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2808 Stained soils & gravel in front of SG 342-28 wellhead**



**Photo # 2814 Meter calibration info not conspicuously posted**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



Photo # 2815 Meter calibration info not conspicuously posted



Photo # 2816 Battery sign missing required information



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2821 Open ended load lines**



**Photo # 2818 Waddles need maintenance/rill erosion/sediment encroaching on equipment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2819 Waddles need maintenance/rill erosion/sediment encroaching on equipment**



**Photo # 2822 Sediment trap needs maintenance (near entrance to spur road)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2825 Ditch needs maintenance (lower tier of pad east side)**



**Photo # 2828 Erosion/ditch needs maintenance (lower tier of pad east side)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2831 Erosion/ditch needs maintenance (lower tier of pad east side)**



**Photo # 2836 Erosion/ditch needs maintenance (upper tier of pad, SW corner near rip rap run)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2845 Tunnel erosion/ditch needs maintenance  
(upper tier of pad, east side)**



**Photo # 2849 Tunnel erosion/ditch needs maintenance  
(upper tier of pad, east side)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2850 Tunnel erosion/berm needs maintenance  
(upper tier of pad, east side)**



**Photo # 2858 Insufficient run on controls/BMP's**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2859 Insufficient run on controls/BMP's**



**Photo # 2860 Insufficient run on controls/BMP's/sediment encroaching on habitat & choking of vegetation**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2861 Insufficient run on controls/BMP's**



**Photo # Insufficient run on controls/BMP's**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2868 Insufficient run on controls/BMP's/sediment encroaching on habitat & choking of vegetation**



**Photo # 2865 Berm needs maintenance (upper tier of past NW side)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2871 Rill erosion/rip rap needs maintenance (upper tier, west side)**



**Photo # 2878 Lack of stabilization**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



Photo # 2879 Lack of stabilization



Photo # 2880 Lack of stabilization



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2887 Rill & tunnel erosion (upper tier of pad, south side)**



**Photo # 2888 Rill & tunnel erosion (upper tier of pad, south side)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL SG 43-28 Pad

Location ID: 334978



**Photo # 2889 Insufficient run on controls/BMP's/ & degradation of roadway (4/10<sup>th</sup> of a mile down lease road)**



**Photo # 2890 Insufficient run on controls/BMP's/ & degradation of roadway (4/10<sup>th</sup> of a mile down lease road)**