

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3223 From entrance to location



Photo # 3224 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3226 Rill erosion/transport of sediment off location/insufficient BMP's



Photo # 3227 Rill erosion on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3228 Rill erosion on spur road



Photo # 3230 Rill erosion on spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3232 Sediment trap needs maintenance



Photo # 3233 Sediment trap needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3234 Rill erosion on spur road



Photo # 3235 Rill erosion on spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



Photo # 3236 Rill erosion on spur road