

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2023

Submitted Date:

03/25/2023

Document Number:

708900159

FIELD INSPECTION FORM

 Loc ID: 335484
 Inspector Name: Smelser, Wayne
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Findings:

- 28 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294181	WELL	PR	08/01/2008	GW	045-15300	CLOUGH RWF 424-13	PR
294182	WELL	PR	08/30/2008	GW	045-15301	CLOUGH RWF 24-13	PR
294190	WELL	PR	08/01/2008	GW	045-15309	CLOUGH RWF 23-13	PR

General Comment:**COGCC Inspection Report Summary**

On 03/24/2023 at approximately 10:52 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 pad.
Location # 335484 in Garfield County Colorado.

Location is located in a High Priority Habitat area/CPW Wildlife Management Plan & in close proximity to NSO/Density Habitat. Location is also 530 yards from the Colorado River & 275 yards from Rifle Creek
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Rill erosion, Transport of sediment off location & Berm, Ditches, Rip Rap & Sediment Trap need maintenance with a CA date of 04/09/2023
2. Meter calibration info not conspicuously posted with a CA date of 04/04/2023
3. Debris/Wildlife Hazard - Barbed wire laying on location with a CA date of 04/01/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Barbed wire laying on location/Wildlife Hazard (barbed wire is near entrance to location)		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.		Date: 04/01/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	04/04/2023
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST			
Comment: Centralized containment						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
Flaring:						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities				
Facility ID:	<u>294181</u>	Type:	<u>WELL</u>	API Number: <u>045-15300</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:		Date:		
Facility ID:	<u>294182</u>	Type:	<u>WELL</u>	API Number: <u>045-15301</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:		Date:		
Facility ID:	<u>294190</u>	Type:	<u>WELL</u>	API Number: <u>045-15309</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Rill erosion
Ditches	Fail					Ditch needs maintenance
Other	Fail					Transportation of sediment off location
Compaction						Light
		Culverts				
Sediment Traps	Fail					Sediment Trap needs maintenance
Rip Rap	Fail					Rip Rap needs maintenance
Berms	Fail					Berm needs maintenance
Gravel						Sparse

Comment:
 1. Rill erosion/sediment encroaching on production unit, more Rill erosion on the east side of tank battery.
 2. Ditches near production unit & sediment trap need maintenance.
 3. Sediment trap needs maintenance - SE corner behind tank battery.
 4. Berm near sediment trap needs maintenance/transportation of sediment off location.
 5. Rip rap around sediment trap needs maintenance.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 04/09/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping, Equipment & Stormwater for observed compliance issues.	smelserw	03/25/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900160	Inspection 708900159 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062694