

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Mar 24, 2023 at 1:21:09 PM
CO



Mar 24, 2023 at 1:21:16 PM
CO

Photo # 3305 From entrance to location

Photo # 3307 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3308 Location



Photo # 3309 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3310 Location



Photo # 3311 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3312 Lack of stabilization



Photo # 3314 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3315 Lack of stabilization



Photo # 3286 Rill erosion

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3287 Rill erosion



Photo # 3288 Rill erosion

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3289 Rill erosion



Photo # 3291 Ditch needs maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3292 Ditch on spur road needs maintenance/light compaction & sparse gravel on road



Photo # 3293 Ditch needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3294 Ditch needs maintenance



Photo # 3295 Rill erosion



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3296 Rill erosion



Photo # 3297 Check dam needs maintenance



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3298 Check dam needs maintenance



Photo # 3299 Check dam needs maintenance



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3300 Ditch & Check dam need maintenance



Photo # 3301 Rip Rap Run needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3302 Rip Rap Run needs maintenance



Photo # 3304 Rill erosion on edge of location