

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2023

Submitted Date:

03/20/2023

Document Number:

708300197

FIELD INSPECTION FORM

 Loc ID 334499 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10433
 Name of Operator: LARAMIE ENERGY LLC
 Address: 1700 LINCOLN ST STE 3950
 City: DENVER State: CO Zip: 80203
Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| , LARAMIE | | cogccnotifications@laramie-energy.com | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 287345 | WELL | PR | 10/01/2022 | GW | 077-09167 | WOODS-SPANGLER 15-11 | PR |
| 287346 | WELL | PR | 06/24/2008 | GW | 077-09166 | WOODS-SPANGLER 15-12 | PR |
| 287347 | WELL | PR | 03/01/2017 | GW | 077-09165 | WOODS-SPANGLER 15-13 | PR |
| 287348 | WELL | PR | 12/11/2007 | GW | 077-09164 | WOODS-SPANGLER 15-14 | PR |
| 287349 | WELL | PR | 04/26/2007 | GW | 077-09163 | WOODS-SPANGLER 21-1 | PR |
| 287350 | WELL | PR | 10/20/2010 | GW | 077-09162 | WOODS-SPANGLER 22-4 | PR |
| 288356 | WELL | PR | 12/29/2007 | GW | 077-09214 | WOODS-SPANGLER 16-16 | PR |

General Comment:[COGCC Inspection Report Summary](#)

On 3/20/2023 at approximately 13:30, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Woods Spangler/15-13 Pad at Location ID #334499 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Multiple wellhead signs illegible
- 2) Wildlife entry hazard at tank battery
- 3) Stormwater; reference stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, Wildlife Management area.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | WELLHEAD | | |
| Comment: | Multiple wellhead signs faded and illegible. | | |
| Corrective Action: | Install signs to comply with Rule 605.g | Date: | 05/20/2023 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------------|-------|--|
| Comment: | 911/1-800-891-6191 | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---------------------------------------|-------|------------|
| Type | OTHER | | |
| Comment: | Wildlife entry hazard at tank battery | | |
| Corrective Action: | Install wildlife protection equipment | Date: | 03/25/2023 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------------|-------|--|
| Type | LOCATION | | |
| Comment: | Wire fencing | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Wire fencing | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Livestock paneling | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 7 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 7 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 7 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 6 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 287345 | Type: | WELL | API Number: | 077-09167 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 287346 | Type: | WELL | API Number: | 077-09166 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 287347 | Type: | WELL | API Number: | 077-09165 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 287348 | Type: | WELL | API Number: | 077-09164 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 287349 | Type: | WELL | API Number: | 077-09163 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 287350 | Type: | WELL | API Number: | 077-09162 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 288356 | Type: | WELL | API Number: | 077-09214 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | | | | |
| Gravel | | | | | | |
| | | Tracking Pad | | | | |
| | | Culverts | | | | |
| Compaction | Fail | | | | | |
| | | Gravel | | | | |
| Berms | | | | | | |
| Ditches | | | | | | |

Comment: [Site degradation from snow plow causing transport of sediment and lack of stabilization](#)

Corrective Action: [Comply with Rule 1002](#)

Date: 04/04/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403350885 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6056718 |
| 708300198 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6056709 |