

Inspection Photos  
Location Name: Sack #44-31  
Spill ID 484022



**Photo 1 – South Excavation groundwater visible with sheen and flecks of hydrocarbon material.**



**Photo 2 – South Excavation, wet stockpile with hydrocarbon odor and no liner.**

Inspection Photos  
Location Name: Sack #44-31  
Spill ID 484022



Photo 3 – South Excavation groundwater visible with sheen and flecks of hydrocarbon material.



Photo 2 – South Excavation groundwater visible with sheen and flecks of hydrocarbon material. Arrows indicate heavily stained material.