

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2023

Submitted Date:

03/27/2023

Document Number:

696204800

**FIELD INSPECTION FORM**

Loc ID: 314671 Inspector Name: Trujillo, Aaron On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		RangelyRegulatory@scoutep.com	Rangely Field
, Chevron	970-257-6004	andrewolson@chevron.com	Operations Superintendent
Sanford, Anita		Anita.Sanford@scoutep.com	Rangely Field
Patterson, Chris		Chris.Patterson@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229231	WELL	PR	10/07/1953	OW	103-06322	A C MCLAUGHLIN 38	RI
314671	LOCATION	AC			-	A C MCLAUGHLIN-62N103W 14NESW	RI

**General Comment:**

On 3/24/2023, Reclamation Specialist Trujillo inspected Chevron USA's A C MCLAUGHLIN 38 location in Rio Blanco County, Colorado.

Well records show Chevron USA Inc as the designated Operator for the Location. Form 9(s) 402890516 transferring the Location/Well from Chevron to Scout Energy management currently "in process". Chevron remains the Operator responsible for the management of the Location until the Form 9 is approved.

The following compliance issues were observed during this inspection:

- Stormwater: Missing or insufficient tracking BMPs on working pad and access road
- Stormwater/Soil stockpiles/Surface Disturbance Minimization: Missing of insufficient BMPs at stockpiles soils
- Stormwater: BMPs missing or insufficient to manage runoff
- Trash/Debris
- Signage

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

See inspection #696204791 and #696204758 regarding tracking issues onto Hwy. 64.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type			
comment:	See "Stormwater" for issues related to the main access road.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location signage in disrepair. See photo 1.		
Corrective Action:	Maintain sign	Date:	04/27/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-675-3700/911		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Pole w/ concrete base observed partially burried next to the utility equipment. See photo 5.		
Corrective Action:	Comply with Rule 606.	Date:	03/31/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229231 Type: WELL API Number: 103-06322 Status: PR Insp. Status: RI

Facility ID: 314671 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment [See "Stormwater" regarding soils placed off-site.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <a href="#">See "Stormwater" under COGCC Comments.</a>						
Corrective Action: <a href="#">Comply with Rule 1002.f.(2)</a>						Date: 03/29/2023
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

<b>COGCC Comments</b>		
Comment	User	Date
<p><b>STORMWATER COMMENTS</b></p> <p>It was observed in this inspection that stormwater, tracking, and erosion control BMPs are missing or insufficient throughout the Location and access road:</p> <p>-BMPs to stabilize, as well as to minimize degradation, tracking and offsite sediment transport are missing or insufficient throughout the Location, and access road leading to the Location; erosion degradation, tracking and sediment transport observed. Access road does not appear to be adequately engineered to manage runoff and to minimize degradation, tracking and sediment transport; refer to inspections #696204791 and #696204758 regarding tracking/sediment transport onto Highway 64.</p> <p>-Operator has pushed/stockpiled soils beyond the perimeter of the working pad area, expanding the disturbance area of the Location; soils are unconsolidated and a pollutant source; BMPs to minimize erosion, degradation, and sediment transport missing or insufficient at stockpiled soils.</p> <p>- BMPs to manage stormwater runoff missing or insufficient on the northeast end of the Location- erosion degradation due to runoff at slope east of the Location evident. Temporary controls required until a long term BMPs to allow for proper discharge can be implemented.</p>	trujilloam	03/27/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204801	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063457</a>