

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Mar 27, 2023 at 1:20:05 PM



Mar 27, 2023 at 1:20:17 PM

Photo # 3452 From entrance to location

Photo # 3453 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 3455 From entrance to location



Photo # 3456 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 3457 Location



Photo # 3458 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



**Photo # 3477 Meter calibration info not conspicuously posted**



**Photo # 3478 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



**Photo # 3460 Rill erosion**



**Photo # 3461 Rill & Gully erosion**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Mar 27, 2023 at 1:24:15 PM



Mar 27, 2023 at 1:24:23 PM

**Photo # 3462 Erosion & Transport of sediment/insufficient run on BMP's**

**Photo # 3463 Erosion & Transport of sediment/insufficient run on BMP's**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



**Photo # 3470 Rill erosion on slope**



**Photo # 3471 Rill erosion on slope**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources